

Project No: **BDHRN002**Job Card No **0023**

Notif.No.: 10049253

Activity: **2001**

Rev No: 20000622

Model.: F900EX

Sheet 1 of 2

A/C Regn: **D-AHRN**

Serial No.: 096

Type: F900EX

Starting Phase: Inspect

Starting Work Centre: FALCON A/C TEAM

Job Description: **SB F900EX-0426**

ETOPS A/C: No

RVSM A/C: No

Warranty: -

ATA: 25

Work Center	
FALCON A/C	

**Zone: 200**

## Corrective Action

0001	<b>SB Effectivity Checked.</b>						 Order: 80069330 Operation: 0010 Phase: Inspect - scheduling activity Work Center:FALCON A/C TEAM
	Accomplished		Inspected				
	Pers. No.	Date	Pers. No.	Date			
	Stamp		Stamp				
Completed & Confirmed on SAP IAW MOE 2.13.							
0002	<b>Divan air curtain(s) Inspected</b>						 Order: 80069330 Operation: 0020 Phase: Inspect - scheduling activity Work Center:FALCON A/C TEAM
	Accomplished		Inspected				
	Pers. No.	Date	Pers. No.	Date			
	Stamp		Stamp				
Completed & Confirmed on SAP IAW MOE 2.13.							
0003	<b>Outcome Recorded</b>						 Order: 80069330 Operation: 0030 Phase: Inspect - scheduling activity Work Center:FALCON A/C TEAM
	Accomplished		Inspected				
	Pers. No.	Date	Pers. No.	Date			
	Stamp		Stamp				
Completed & Confirmed on SAP IAW MOE 2.13.							

OEM Code: SB F900EX-0426

Form No: JA-SAP-MTX-002

Operator Code: SB 0426

Printed by: ADAMOVIC G

Project No: **BDHRN002**Job Card No **0023**

Notif.No.: 10049253

Activity: **2001**

Rev No: 20000622

Model.: F900EX

Sheet 2 of 2

A/C Regn: **D-AHRN**

Serial No.: 096

Type: F900EX

Starting Phase: Inspect

Starting Work Centre: FALCON A/C TEAM

Job Description: **SB F900EX-0426**

ETOPS A/C: No

RVSM A/C: No

Warranty: -

ATA: 25


Work Center	
FALCON A/C	

0004	<b>Divan air curtain Removed &amp; Re-Installed</b>						 Order: 80069330 Operation: 0040 Phase: Inspect - scheduling activity Work Center:FALCON A/C TEAM
	Accomplished		Inspected				
	Pers. No.	Date	Pers. No.	Date			
	Stamp		Stamp				
Completed & Confirmed on SAP IAW MOE 2.13.							
0005	<b>SB in appropriate aircraft Recorded documents</b>						 Order: 80069330 Operation: 0050 Phase: Inspect - scheduling activity Work Center:FALCON A/C TEAM
	Accomplished		Inspected				
	Pers. No.	Date	Pers. No.	Date			
	Stamp		Stamp				
Completed & Confirmed on SAP IAW MOE 2.13.							
<b>Defect Card Raised</b>							

Components Removed/Installed					
	Part Number	Part Name	S/N	Location	Comm. Off/On
OFF					
ON					
OFF					
ON					
OFF					
ON					
OFF					
ON					

Occurance Report Raised? YES ☐

Operations Above &amp; Notifications Completed IAW MOE 2.13.



OEM Code: SB F900EX-0426

Operator Code: SB 0426

Form No: JA-SAP-MTX-002

Printed by: ADAMOVIC G



Printed: 03.09.2012

13:34:17

Print No: 1

Operator: **HERON AVIATION**

Work Card No.: **0426**

Serial No.: **096**

Model: **FALCON 900EX**

Reg No.: **D-AHRN**

Workorder No.: \_\_\_\_\_

	Date	A/C HRS	AFL	APH			
Due At	<b>25-NOV-2012</b>	<b>4410:47</b>					
Accomplished							

TECHNICIAN SIGNATURE: \_\_\_\_\_ KIND OF CERTIFICATE & NO.: \_\_\_\_\_

INSPECTED BY: \_\_\_\_\_ KIND OF CERTIFICATE & NO.: \_\_\_\_\_

>SB 0426

**EQUIPMENT AND FURNISHINGS – PASSENGER COMPARTMENT – REMOVAL OF DIVAN AIR CURTAIN  
SERVICE BULLETIN**

COMPLIANCE WITH THIS SERVICE BULLETIN SHOULD BE DONE DURING THE NEXT "2A" INSPECTION

☐ COMPLIED WITH

☐ DECLINED

☐ DEFERRED

☐ NOT APPLICABLE

*All text added to the "Note" field will be presented as part of the MOC selection through the application.  
Ex: MOC of "Complied With" and a Note of "At Manufacture" will display as "Complied With - At Manufacture"*

Compliance Note: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

TECH \_\_\_\_\_

INSP \_\_\_\_\_

LABOR-HRS  
HRS.THS \_\_\_\_\_

Operator: **HERON AVIATION**

Work Card No.: **0426**

Serial No.: **096**

Model: **FALCON 900EX**

Reg No.: **D-AHRN**

Workorder No.: \_\_\_\_\_

**SOURCE SUMMARIES**

**999 BULLETINS PAGE NO.:0426**

0426

EQUIPMENT AND FURNISHINGS – PASSENGER COMPARTMENT – REMOVAL OF DIVAN AIR CURTAIN SERVICE  
BULLETIN

# FALCON *SERVICE BULLETIN ADVISORY*

DASSAULT AVIATION  
SERVICE BULLETIN :

F900EX-426

DATE:

December 5, 2011

ATA CHAPTER: 25

COVERED MOD: R2454

TITLE: **EQUIPMENT AND FURNISHINGS – PASSENGER  
COMPARTMENT – REMOVAL OF DIVAN AIR CURTAIN**

EFFECTIVITY: 

- F900EX aircraft with serial numbers 1 through 239, 241, 243 through 249 and 251 through 255 (F900EX, F900EX EASy, F900LX),
- F900EX aircraft with serial numbers 601 through 624 (F900DX), equipped with side facing divan(s) that have a fabric cover on the back side

REASON: On aircraft in service, the side facing divan outboard curtain / blanket may have been installed without approved data. In addition, some of the materials do not consistently pass regulatory burn requirements.  
The air curtain / blanket is attached to the outboard side of the divan using hook and loop fasteners.  
The purpose of this Service Bulletin is to inspect and remove the air curtain if installed.

## CRITERIA

	Corrosion Prevention		Cockpit/Operations Improvements
	Dispatch - Reliability		Cabin Comfort
	Operational Availability Damage prevention		New Technology New Regulations
X	Manufacturer's Suggested		

DESCRIPTION: This procedure consists in:  

- Inspecting side facing divans for air curtain,
- Removing air curtain(s) if installed.

RELATED SB's: None

COMPLIANCE: **Compliance with this Service Bulletin should be done during the next "2A" inspection.**

LABOR-HRS  
ALLOWANCE: 2 hours

*Note : labor hours concern only the work described in this Service Bulletin and do not include other maintenance work which may be performed on this occasion.*

MATERIAL INFORMATION: Excluding locally procured material.

PART NUMBER TO ORDER	QTY	2011 VAT FREE UNIT PRICE (US\$)	REMARKS
None			

COMMERCIAL PROGRAM: 2 labor-hours are free of charge until June 30, 2013.

FALCONCARE COVERAGE: Full coverage until June 30, 2013.

NOTE: Claims for labor should not exceed the labor hours allowance indicated above.

**TO ORDER, CONTACT YOUR DASSAULT FALCON SPARES ACCOUNT REPRESENTATIVE**  
Prices are subject to change without notice

# ***FALCON SERVICE BULLETIN***

## **FALCON 900EX FALCON 900EX EASy FALCON 900LX FALCON 900DX**

**No 426**

**DECEMBER 05, 2011**

**ATA 25-34**

**EQUIPMENT AND FURNISHINGS  
PASSENGER COMPARTMENT  
REMOVAL OF DIVAN AIR CURTAIN**

Copyright © 2011 by Dassault Aviation  
All rights reserved. No part of this work may be reproduced or copied  
in any form or by any means without written permission  
of Dassault Aviation.

**FALCON 900EX****F900EX-426**

**EQUIPMENT AND FURNISHINGS  
PASSENGER COMPARTMENT  
REMOVAL OF DIVAN AIR CURTAIN**

---

**Initial issuance**

December 05, 2011

List of effective pages :  
1 to 4

---

**FALCON 900EX****F900EX-426****EQUIPMENT AND FURNISHINGS  
PASSENGER COMPARTMENT  
REMOVAL OF DIVAN AIR CURTAIN****1. PLANNING INFORMATION****A. EFFECTIVITY**

This Service Bulletin is applicable to:

- F900EX aircraft with serial numbers 1 through 239, 241, 243 through 249 and 251 through 255 (F900EX, F900EX EASy, F900LX),
- F900EX aircraft with serial numbers 601 through 624 (F900DX),

equipped with side facing divan(s) that have a fabric cover on the back side.

**B. REASON**

On aircraft in service, the side facing divan outboard curtain / blanket may have been installed without approved data. In addition, some of the materials do not consistently pass regulatory burn requirements. The air curtain / blanket is attached to the outboard side of the divan using hook and loop fasteners.

The purpose of this Service Bulletin is to inspect and remove the air curtain if installed.

**C. DESCRIPTION**

This procedure consists in:

- Inspecting side facing divans for air curtain,
- Removing air curtain(s) if installed.

**D. COMPLIANCE**

Compliance with this Service Bulletin should be done during the next "2A" inspection.

**E. APPROVAL**

This Service Bulletin covers DASSAULT AVIATION modification FALCON F900EX R2454 which has been approved under the authority of DOA nr. EASA.21J.051.

The technical content of this document is approved under the authority of DOA nr. EASA.21J.051.

**F. LABOR**

Estimated labor-hours: Refer to Falcon Service Bulletin Advisory

**NOTE:** These labor-hours only concern the work described in this Service Bulletin and do not include other maintenance work which may be performed on this occasion.

**G. MATERIAL - PRICE AND AVAILABILITY**

The modification kit may be obtained from either address listed below:



**FALCON 900EX**
**F900EX-426**

Western hemisphere: DASSAULT FALCON JET CORP.  
 SPARES DISTRIBUTION CENTER  
 200 RISER ROAD  
 LITTLE FERRY, NJ 07643 U.S.A.  
 Telephone:  
 • CANADA and U.S.A.: 1-800-800-4036  
 • MEXICO: 001-800-800-4036  
 • Other countries: 1-201-541-4809  
 Fax:  
 • CANADA and U.S.A.: 1-800-800-4817  
 • MEXICO: 001-800-800-4817  
 • Other countries: 1-201-440-7021

Other continents: DASSAULT AVIATION  
 Falcon Spares  
 BOITE POSTALE N°101  
 AEROPORT DU BOURGET  
 93350 - LE BOURGET Cedex (FRANCE)  
 Please contact your Dassault Aviation  
 Account Representative  
 Telephone: 33 (0)1.48.35.56.78  
 Fax: 33 (0)1.48.35.56.00

Price and availability on request.

**H. TOOLING - PRICE AND AVAILABILITY**

Normal maintenance tooling.

**I. WEIGHT AND BALANCE**

Change in weight: None.

Change in balance with respect to 25% MAC: None.

**J. REFERENCES**

Supplemental Maintenance Manual:

- ATA 25 Divan Removal and Installation

Aircraft Maintenance Manual:

- GENERAL MAINTENANCE AND SAFETY PRECAUTIONS (Refer to [TASK 20-00-00-910-801](#))

**K. OTHER PUBLICATIONS AFFECTED**

None.

**FALCON 900EX****F900EX-426****2. ACCOMPLISHMENT INSTRUCTIONS****A. PRELIMINARY STEPS**

- (1) The aircraft must be in the maintenance configuration (Refer to [TASK 20-00-00-910-801](#)).
- (2) Remove one of the divan drawers to facilitate inspection for divan air curtain(s) (Refer to Supplemental Maintenance Manual ATA 25).
- (3) Inspect divan(s) for an outboard divan air curtain (Refer to [fig. 1](#)) . If present, continue with service bulletin. If divan(s) air curtain is not installed, no further action required.

**B. MODIFICATION INSTRUCTIONS**

Refer to [fig. 1](#).

- (1) Remove divan air curtain(s) from aircraft and dispose (Refer to [fig. 1](#)).

NOTE: Depending on the aircraft configuration, the removal of the divan may be necessary.

**C. FINAL STEPS**

- (1) Re-install divan drawer Refer to Supplemental Maintenance Manual.

**D. RECORDING**

Record compliance with this Service Bulletin in the appropriate aircraft documents.

Fill out the card located at the end of the Service Bulletin and mail or fax it to Dassault Aviation or Dassault Falcon Jet, or fill out the electronic Service Bulletin reply form located in the "Service Bulletin" page on the Falcon portal.



**Figure 1: EXISTING DIVAN AIR CURTAIN**

FROM \_\_\_\_\_

\_\_\_\_\_

ZIP CODE \_\_\_\_\_



NO POSTAGE  
NECESSARY  
IF MAILED  
IN THE  
UNITED STATES



**BUSINESS REPLY MAIL**

FIRST CLASS MAIL PERMIT NO. 3306 HACKENSACK, NJ 07602

**POSTAGE WILL BE PAID BY ADDRESSEE:**

DASSAULT FALCON JET CORP.  
PO BOX 1946  
SO HACKENSACK NJ 07606-9946

ATTENTION:  
FIELD SERVICE DEPARTMENT



DASSAULT AVIATION  
78, Quai Marcel Dassault  
Cedex 300  
92552 SAINT-CLOUD Cedex  
FRANCE

A l'attention de DSC

## SERVICE BULLETINS COMPLIANCE

**FALCON 900EX** A/C S/N

--	--	--	--

DASSAULT AVIATION Number

F900EX	426
--------	-----

ATA Number

F900EX	25	34
--------	----	----

☐ Coding:

**C** complete compliance  
**T** partial compliance

--	--

--	--	--

☐

--	--

--	--	--

☐

Performed by:

Remarks: Initial issuance

Date:

Signature:

## SERVICE BULLETINS COMPLIANCE

Would you be kind enough to inform us that this Service Bulletin is complied with:

- For "Western Hemisphere", mail upper card (No postage necessary if mailed in the U.S.A.) or fax to Dassault Falcon Jet: 1-201-541-4700.
- For "Other Continents", mail card herebelow or fax to Dassault Aviation: 33 (0)1.47.11.65.21.

On the occasion, if other Service Bulletins have been simultaneously complied with could you complete the blank spaces provided for this purpose.

## APPLICATION DE BULLETINS DE SERVICE

Lorsque vous aurez applique ce Bulletin de Service sur votre avion, veuillez avoir l'amabilite de nous en informer:

- Utiliser la carte reponse superieure pour continent americain (Dispensee de timbrage pour postage depuis les U.S.A.) ou le fax pour Dassault Falcon Jet : 1-201-541-4700.

- Ou la carte reponse inferieure pour autres continents ou le fax pour Dassault Aviation : 33 (0)1.47.11.65.21.

Eventuellement, si d'autres Bulletins de Service ont ete appliques simultanement, vous pouvez les mentionner dans les cases vierges prevues a cet effet.

## APPLICATION DES BULLETINS DE SERVICE

### SERVICE BULLETINS COMPLIANCE

**FALCON 900EX** A/C S/N

--	--	--	--

DASSAULT AVIATION Number

Numero DASSAULT AVIATION

F900EX	426
--------	-----

ATA Number

Numero ATA

F900EX	25	34
--------	----	----

☐ Coding:

**C** complete compliance  
application totale  
**T** partial compliance  
application partielle

--	--

--	--	--

☐

--	--

--	--	--

☐

Performed by:  
Fait par:

Remarks: Initial issuance

Date:

Signature:

Remarques: Edition originale