

Project No: **BDHRN002**Job Card No **0012**

Notif.No.: 10049217

Activity: **1022**

Rev No: 20000622

Model.: F900EX

Sheet 1 of 2

A/C Regn: **D-AHRN**

Serial No.: 096

Type: F900EX

Starting Phase: Remove

Starting Work Centre: FALCON A/C TEAM

Job Description: **SERV EPS 3**

ETOPS A/C: No

RVSM A/C: No

Warranty: -

ATA: 33

Work Center	
FALCON A/C	
MTX AVIO DEPT	
COMPONENT	

**Zone: 200****Access Required for this task:**

PAX

## Corrective Action

0001	<b>Access Performed</b>						 Order: 80069303 Operation: 0010 Phase: Remove - scheduling activity Work Center:FALCON A/C TEAM
	Accomplished		Inspected				
	Pers. No.	Date	Pers. No.	Date			
	Stamp		Stamp				
	Completed & Confirmed on SAP IAW MOE 2.13.						
0002	<b>Task carried out in accordance with the attached Customer Card that quotes the Operator code detailed below.</b>						 Order: 80069303 Operation: 0020 Phase: Remove - scheduling activity Work Center:MTX AVIO DEPT
	Accomplished		Inspected				
	Pers. No.	Date	Pers. No.	Date			
	Stamp		Stamp				
	Completed & Confirmed on SAP IAW MOE 2.13.						
0003	<b>Task carried out in accordance with the attached Customer Card that quotes the Operator code detailed below.</b>						 Order: 80069303 Operation: 0030 Phase: Remove - scheduling activity Work Center:COMPONENT RPR
	Accomplished		Inspected				
	Pers. No.	Date	Pers. No.	Date			
	Stamp		Stamp				
	Completed & Confirmed on SAP IAW MOE 2.13.						

OEM Code: 33-50-33-610-801-03

Form No: JA-SAP-MTX-002

Operator Code: 33-50-33-610-801-03

Printed by: ADAMOVIC G



Printed: 03.09.2012

13:34:17

Print No: 1

Project No: **BDHRN002**Job Card No **0012**

Notif.No.: 10049217

Activity: **1022**

Rev No: 20000622

Model.: F900EX

Sheet 2 of 2

A/C Regn: **D-AHRN**

Serial No.: 096

Type: F900EX

Starting Phase: Remove

Starting Work Centre: FALCON A/C TEAM

Job Description: **SERV EPS 3**

ETOPS A/C: No

RVSM A/C: No

Warranty: -

ATA: 33


Work Center	
FALCON A/C	
MTX AVIO DEPT	
COMPONENT	

0004	<b>Access Closed</b>						Order: 80069303 Operation: 0040 Phase: Remove - scheduling activity Work Center:FALCON A/C TEAM
	Accomplished		Inspected				
	Pers. No.	Date	Pers. No.	Date			
	Stamp		Stamp				
Completed & Confirmed on SAP IAW MOE 2.13.							
<b>Defect Card Raised</b>							

Components Removed/Installed					
	Part Number	Part Name	S/N	Location	Comm. Off/On
OFF					
ON					
OFF					
ON					
OFF					
ON					
OFF					
ON					

Occurance Report Raised? YES ☐

Operations Above &amp; Notifications Completed IAW MOE 2.13.



OEM Code: 33-50-33-610-801-03

Operator Code: 33-50-33-610-801-03

Form No: JA-SAP-MTX-002

Printed by: ADAMOVIC G



Printed: 03.09.2012

13:34:17

Print No: 1

Operator: **HERON AVIATION**

Work Card No.: **33.190**

Serial No.: **096**

Model: **FALCON 900EX**

Reg No.: **D-AHRN**

Workorder No.: \_\_\_\_\_

Due At	Date	A/C HRS	AFL	APH			
Accomplished	<b>25-JAN-2013</b>						

TECHNICIAN SIGNATURE: \_\_\_\_\_ KIND OF CERTIFICATE & NO.: \_\_\_\_\_

INSPECTED BY: \_\_\_\_\_ KIND OF CERTIFICATE & NO.: \_\_\_\_\_

33-50-33-900-801-03

CABIN EMERGENCY LIGHTING (EPS 3) POWER SUPPLY

AMM 33-50-33-900-801

REASON REMOVED: (CHECK ONE)	<input type="checkbox"/> TIME EXPIRED	<input type="checkbox"/> FAILURE	<input type="checkbox"/> WORN	<input type="checkbox"/> LOANER	<input type="checkbox"/> SCHEDULING CONV
	<input type="checkbox"/> MOD/UPGRADE	<input type="checkbox"/> SERVICE	<input type="checkbox"/> ENGINE CHANGE	<input type="checkbox"/> TIRE CHANGE	<input type="checkbox"/> SWAP/TRBLE SHOOT
					<input type="checkbox"/> DAMAGED
					<input type="checkbox"/> UNKNOWN

*If removed P/N & S/N information is incorrect please provide details below.*

REMOVED P/N	D734-02-001		S/N	1426		LABOR-HRS	
INSTALLED P/N			S/N			PART COST\$	
INSTALLED TSN	MOS		INSTALLED TSO	MOS		TIME SINCE REPAIR	MOS
	HRS			HRS			HRS
	LDGS			LDGS		WARRANTY TIME REMAINING	LDGS
						TECH:	INSP:

REMARKS : \_\_\_\_\_

Note: INITIAL THE SERVICE TASKS BELOW WHICH WERE ACCOMPLISHED DURING CHANGE. IF TASKS WERE NOT ACCOMPLISHED, RECORD TIME ACCRUED SINCE TASK WAS LAST ACCOMPLISHED OR CHECK CONTINUE TIME (CT).

TECH	INSP	LABOR-HRS HRS.MINS	TIME ACCRUED	CONTINUE TIME
------	------	-----------------------	-----------------	------------------

33-50-00-720-801-03 FUNCTIONAL TEST NO.3 EMERGENCY LIGHTING (EPS 3) POWER SUPPLY SYSTEM

REMARKS : \_\_\_\_\_

AMM 33-50-00-720-801

#>33-50-33-610-801 SERVICING NO.3 EMERGENCY LIGHTING (EPS 3) POWER SUPPLY

RECORD DATE OF SERVICE \_\_\_\_/\_\_\_\_/\_\_\_\_

AMM 33-50-33-610-801

REMARKS : \_\_\_\_\_

33-50-37-960-802-03 DISCARD CABIN EMERGENCY LIGHTING (EPS 3) POWER SUPPLY BATTERY PACK

REMARKS : \_\_\_\_\_

AMM 33-50-37-960-802

Operator: **HERON AVIATION**

Work Card No.: **33.190**

Serial No.: **096**

Model: **FALCON 900EX**

Reg No.: **D-AHRN**

Workorder No.: \_\_\_\_\_

**AREA SUMMARIES**

**F4 PASSENGER CABIN**

33-50-33-900-801-03 CABIN EMERGENCY LIGHTING (EPS 3) POWER SUPPLY

**SOURCE SUMMARIES**

**956 MPD 05-20-33 PAGE NO.:PAGE 1/2 REF: 33-50 EMERGENCY LIGHTING DATE: MAR 09/2012 2**

33-50-00-720-801-03 FUNCTIONAL TEST NO.3 EMERGENCY LIGHTING (EPS 3) POWER SUPPLY SYSTEM

33-50-33-610-801-03 SERVICING NO.3 EMERGENCY LIGHTING (EPS 3) POWER SUPPLY

**956 MPD 05-20-33 PAGE NO.:PAGE 2/2 REF: 33-50 EMERGENCY LIGHTING DATE: MAR 09/2012 2**

33-50-37-960-802-03 DISCARD CABIN EMERGENCY LIGHTING (EPS 3) POWER SUPPLY BATTERY PACK

**971 SMM 05-20-00 PAGE NO.:PAGE 3 REF: 33 - BATTERY DATE: MAR 09/12 B**

33-50-37-960-802-03 DISCARD CABIN EMERGENCY LIGHTING (EPS 3) POWER SUPPLY BATTERY PACK