

Project No: **BDHRN002**Job Card No **0022**

Notif.No.: 10049209

Activity: **1014**

Rev No: 20000622

Model.: F900EX

Sheet 1 of 1

A/C Regn: **D-AHRN**

Serial No.: 096

Type: F900EX

Starting Phase: Inspect

Starting Work Centre: FALCON A/C TEAM

Job Description: **INSP LH Pilot Life Vest**

ETOPS A/C: No

RVSM A/C: No

Warranty: -

ATA: 25

Work Center	
FALCON A/C	

Zone: 200**Access Required for this task:**

PAX

Corrective Action

0001	Task carried out in accordance with the attached Customer Card that quotes the Operator code detailed below.					 Order: 80069245 Operation: 0010 Phase: Inspect - scheduling activity Work Center: FALCON A/C TEAM
	Accomplished		Inspected			
	Pers. No.	Date	Pers. No.	Date		
	Stamp		Stamp			

Completed & Confirmed on SAP IAW MOE 2.13.

Defect Card Raised

Components Removed/Installed

	Part Number	Part Name	S/N	Location	Comm. Off/On
OFF					
ON					
OFF					
ON					
OFF					
ON					
OFF					
ON					

Occurance Report Raised? YES ☐

Operations Above & Notifications Completed IAW MOE 2.13.

OEM Code: 25-64-17-200-802-01

Operator Code: 25-64-17-200-802-01

Form No: JA-SAP-MTX-002

Printed by: ADAMOVIC G



Printed: 03.09.2012

13:34:17

Print No: 1

Operator: **HERON AVIATION**

Work Card No.: **25.100**

Serial No.: **096**

Model: **FALCON 900EX**

Reg No.: **D-AHRN**

Workorder No.: _____

	Date	A/C HRS	AFL	APH			
Due At	02-JUL-2017						
Accomplished							

TECHNICIAN SIGNATURE: _____ KIND OF CERTIFICATE & NO.: _____

INSPECTED BY: _____ KIND OF CERTIFICATE & NO.: _____

25-64-17-900-802-01

☐ PILOT LIFE VEST

GENERIC NO REF

REASON REMOVED: (CHECK ONE)	<input type="checkbox"/> TIME EXPIRED	<input type="checkbox"/> FAILURE	<input type="checkbox"/> WORN	<input type="checkbox"/> LOANER	<input type="checkbox"/> SCHEDULING CONV
	<input type="checkbox"/> MOD/UPGRADE	<input type="checkbox"/> SERVICE	<input type="checkbox"/> ENGINE CHANGE	<input type="checkbox"/> TIRE CHANGE	<input type="checkbox"/> SWAP/TRBLE SHOOT
					<input type="checkbox"/> DAMAGED
					<input type="checkbox"/> UNKNOWN

If removed P/N & S/N information is incorrect please provide details below.

REMOVED P/N	63600-505		S/N	L709396		LABOR-HRS	
INSTALLED P/N			S/N			PART COST\$	
INSTALLED TSN	MOS	INSTALLED TSO	MOS	TIME SINCE REPAIR	MOS	WARRANTY TIME REMAINING	MOS
	HRS		HRS		HRS		HRS
	LDGS		LDGS		LDGS		LDGS
						TECH:	INSP:

REMARKS : _____

Note: INITIAL THE SERVICE TASKS BELOW WHICH WERE ACCOMPLISHED DURING CHANGE. IF TASKS WERE NOT ACCOMPLISHED, RECORD TIME ACCRUED SINCE TASK WAS LAST ACCOMPLISHED OR CHECK CONTINUE TIME (CT).

TECH	INSP	LABOR-HRS HRS.MINS	TIME ACCRUED	CONTINUE TIME
------	------	-----------------------	-----------------	------------------

#>25-64-17-200-802 INSPECTION PILOT LIFE VEST -01

RECORD DATE OF INSPECTION ____/____/____

GENERIC NO REF,AMM REMARKS :
25-64-17-200-802

25-64-17-350-802-01 RESTORATION PILOT LIFE VEST (OVERHAUL OR DISCARD)

REMARKS : _____

AMM
25-64-17-350-802,GEN
ERIC CMM

Operator: **HERON AVIATION**

Work Card No.: **25.100**

Serial No.: **096**

Model: **FALCON 900EX**

Reg No.: **D-AHRN**

Workorder No.: _____

AREA SUMMARIES

F3 COCKPIT

25-64-17-900-802-01 PILOT LIFE VEST

25-64-17-200-802-01 INSPECTION PILOT LIFE VEST

SOURCE SUMMARIES

956 MPD 05-20-25 PAGE NO.:PAGE 2/3 REF: 25-60 EMERGENCY EQUIPMENT DATE: MAR 09/2012 2

25-64-17-200-802-01 INSPECTION PILOT LIFE VEST

25-64-17-350-802-01 RESTORATION PILOT LIFE VEST (OVERHAUL OR DISCARD)

971 SMM 05-20-00 PAGE NO.:PAGE 1 REF: 25 - LIFE VEST DATE: MAR 09/12 B

25-64-17-200-802-01 INSPECTION PILOT LIFE VEST

Operator: **HERON AVIATION**

Work Card No.: **25.100**

Serial No.: **096**

Model: **FALCON 900EX**

Reg No.: **D-AHRN**

Workorder No.: _____

Procedural Text

25-64-17-350-802-01

REFER TO APPLICABLE COMPONENT MAINTENANCE MANUAL (CMM) FOR PROCEDURE(S) .

FALCON 900EX AIRCRAFT MAINTENANCE MANUAL

TASK 25-64-17-200-802 INSPECTION OF THE CREW LIFE VESTS

1. OVERVIEW OF THE JOB

Operation codes:

- 25-64-17-200-802-01 LH pilot life vest (**L10ME**)
- 25-64-17-200-802-02 RH pilot life vest (**R10ME**)
- 25-64-17-200-802-03 third crew member life vest (**M10ME**)

This task consists in a check of the life preserver package (visible holes, tears or tips).

FALCON 900EX AIRCRAFT MAINTENANCE MANUAL

TASK 25-64-17-350-802

RESTORATION OF THE CREW LIFE VESTS (OVERHAUL OR DISCARD)

1. OVERVIEW OF THE JOB

Operation codes:

- 25-64-17-350-802-01 LH pilot life vest (**L10ME**)
- 25-64-17-350-802-02 RH pilot life vest (**R10ME**)
- 25-64-17-350-802-03 third crew member life vest (**M10ME**)

This task consists of an overhaul of the life vests.

An alternative solution is to replace the life vests with new ones.